

STREET	No. of houses	NOTES	PAVEMENT RATING (red / amber / green)	ROAD RATING (red / amber / green)
A875 - through road - in/out of village		Road surface poor on way in / out of village - works required	n/a	amber
ALDER CRESCENT	7		green	green
ALLAN ROAD	49	1.The entire pavement on the left hand side going down from Endrick Road should be replaced and the kerbs reset. 2.On the opposite side, pavement patching is required at numbers 4,14,20,28,30,36,38,40,42. At number 28, the depression results from a water board repair in 2015.	red	amber
BALFRON ROAD	27	Balfron Road pavement from Health Centre to outskirts of village - v poor. Corner at old bank building - road re-marking very urgent.	red	red
BEECH DRIVE	21	Some resurfacing required to patch of road between Abbeyfield and top of Maple Cresc.	green	green / amber
BIRCH ROAD	30		amber - v patchy	green
BOQUHAN	26		n/a	green
BRANZIERT ROAD	15		green	amber
BRANZIERT ROAD NORTH	43		green	green
BUCHANAN ROAD	38	The pavements in Buchanan Road and Graham Road are in a poor state of repair. There are a number of elderly people in these areas, who walk to the shops who have mobility problems, some using walking aids. Uneven, potholed pavements could cause them to fall and injure themselves especially, when frosty or icy. pavements in poor condition - v patchy The road junctions between Buchanan Rd. & Graham Rd. and Buchanan Rd. and Crosshead Rd. works required	red	green / amber
CEDAR ROAD	16	Recently resurfaced - but one patch at junction Beech Dr. tbc.	green	green
CHESTNUT AVENUE	15	not adopted - bricked road		
CROSSHEAD ROAD	13	The road junction between Buchanan Rd. & Crosshead Rd. works required	amber - v patchy	amber
DRUMBEG LOAN	32	Road surface v poor at bottom end - top end has been resurfaced recently - water drains down middle of the road.	n/a - restricted	green / amber
DRUMORE ROAD	9		green	green

DRUMTIAN ROAD	20	Top at Balfron Road needs patching. Road edge needs reinstated half way down and pot holes at bottom require to be filled.	n/a - restricted	green / amber
ELDER ROAD	16	recently resurfaced	green	green
ELM ROAD	6	recently resurfaced	green	green
ENDRICK ROAD	11	not adopted		
GARTNESS ROAD	15	Gartness Road has a very deep area gouged out on the way out of the village - overall has considerable damage to the verges.	n/a - restricted	green
GRAHAM ROAD	35	The pavements in Buchanan Road and Graham Road are in a poor state of repair. There are a number of elderly people in these areas, who walk to the shops who have mobility problems, some using walking aids. Uneven, potholed pavements could cause them to fall and injure themselves especially, when frosty or icy. pavements in poor condition - v patchy. The road junction between Buchanan Rd. & Graham Rd. - works required	red	green / amber
GREENEND LANE	2		amber	green
GREENEND ROAD	5		green	green
HARPERS ROAD	24	recently resurfaced	green	green
KIRKHOUSE ROAD	8		green	green
LAMPSON LANE	9		green	green
LAMPSON LOAN	4		green	green
LAMPSON ROAD	48	1.Pavement repairs are needed at numbers 1,7,8,9,24,35 and 49. 2.Potholes in the road need to be filled at the corner outside no 12 and at the junction with Lampson Lane and at the road end outside Harley. 3. Road patching is required at the junction with Napier Road and outside no 22.	amber	amber
MAIN STREET	40	1 - CoOp : Road condition from Old Bank to Church is poor and work required. Main Street pavement from the Old Bank to the Wellgreen is unsafe for elderly people and pushchair traffic. Pavement from WellGreen to the CoOp needs work to remove puddles.	red	green
MAIN STREET	17	2. CoOp - Beech Drive	red	green
MAIN STREET	30	3. Beech Drive to Drumbeg Loan - pavement from the top of Beech Drive to Drumbeg Loan - works required, worse at Beech Drive end.	red	amber

MAPLE CRESCENT	19	some parts of pavement very mossy / slippery	green	green
NAPIER ROAD	17	1.Pavement repairs are required at number 6 and over the road from this. 2.Road repairs are required outside numbers 10/12 and the road should be resurfaced from this to the junction with Lampson Road. 3.The pavement needs to be reformed from number 11 to the junction with Lampson Road.	amber	amber
NEW ENDRICK ROAD	28	1.The road needs to be resurfaced at the junction with Lampson Road. 2.The pavement needs to be resurfaced at numbers 40 and 42. 3.Drains are collapsing in road outside numbers 19,27 and 40.	green / amber	green / amber
OAK PLACE	9		green	green
ROWAN CRESCENT	27		green	green
STATION ROAD	34	1.From bus stop on church side for safety need to extend yellow lines to meet one another. It is dangerous when due to parking only one lane is available. 2.Pavement on Glebe side needs to be replaced with kerbs raised from Glasgow/Balfron sign to post box opposite Buchanan Views. 3.Road repair required at entrance to Stockinghill. 4.One drain is collapsing opposite the lamp post at the entrance to Buchanan Views. 5.The pavement has collapsed at the post box and needs to be repaired. 6.A 1m square patch is sinking in the road at the substation. 7.Manhole repairs are required at Endrick Road. 8.A deep pothole in Drumore Road needs to be filled. 9.The recently resurfaced pavement is cracking at the 40mph limit sign. 10.The services repair crossing the road at the 40 limit sign is sinking and needs to be repaired. 11.A repair to stop subsidence is required at the junction with	red - on section from Balfron Rd. down to Gartness Rd.	amber
THE OAKS	17		green	green
THE SQUARE	10	no work required	green	green
total	792			
Red – in immediate need of repair	red			
Amber – repairs / resurfacing require	amber			
Green – condition acceptable for now	green			